
PACKING INSTRUCTIONS **MINI SECURITY CAGES**

TIA WILL PROVIDE THE FOLLOWING

- Mini security cage weight 50 kg (W72 x D80 x H98 cm)
- Recycled paper for wrapping
- Strips for locking
- Black plastic cover for wrapping



Maximum weight capacity is 250 kg

HOW TO PACK



Laptops and desktops <u>must</u> be packed as shown.

<u>NOTE:</u> Make sure the heaviest equipment is packed at the bottom. All printers and desktops should be placed on the bottom shelf.



The recycled paper should be placed in the peripheral areas in order to protect the devices during transportation.





PACKING PERIPHERALS

PERIPHERALS COULD BE:

Cables

Docking stations

Network equipment

Keyboard, mice etc.



Place the peripherals in boxes as shown.

NOTE: The peripherals must be sorted and packed separately.

LOCKING THE CAGE




MAKE SURE:

- Not to overload the cage
- There is no free space between the devices.
- The equipment stays stable.
- To lock the cage with the supplied strip. •

NOTE: Please do not open or remove the blue plastic pocket.

PREPARE CAGE FOR SHIPPING



Isolate the cage with the black protective cover.

Attach the KO-number and the UN3481 Caution sign on all sides.



Download the sign here





